









d_0	$\varnothing 8\text{mm}$







A8 $h_{\text{nom}} = 70\text{mm} \mid t_{\text{fix}2} = 0 \dots 10\text{mm}$

HUS3-H 8	$t_{\text{fix}1}$	$t_{\text{fix}1} + t_{\text{fix}2}$
8x75	5 mm	5...15 mm
8x85	15 mm	15...25 mm
8x100	25 mm	30...40 mm
8x120	35 mm	50...60 mm
8x150	50 mm	80...90 mm






d_0	$\varnothing 8\text{mm}$	$\varnothing 8\text{mm}$	$\varnothing 6\text{mm}$























B5

	$h_{\text{nom}1}$	$h_{\text{nom}2}$	$h_{\text{nom}3}$
HUS3-H 8	=50mm	=60mm	=70mm
	$t_{\text{fix}1}$	$t_{\text{fix}2}$	$t_{\text{fix}3}$
8x55	5 mm	-	-
8x65	15 mm	5 mm	-
8x75	25 mm	15 mm	5 mm
8x85	35 mm	25 mm	15 mm
8x100	50 mm	40 mm	30 mm
8x120	70 mm	60 mm	50 mm
8x150	100 mm	90 mm	80 mm



		d_0
		$\varnothing 8\text{mm}$





B5

HUS3-H 8	h_{nom1} =50mm	h_{nom2} =60mm	h_{nom3} =70mm
	t_{fix1}	t_{fix2}	t_{fix3}
8x55	5 mm	-	-
8x65	15 mm	5 mm	-
8x75	25 mm	15 mm	5 mm
8x85	35 mm	25 mm	15 mm
8x100	50 mm	40 mm	30 mm
8x120	70 mm	60 mm	50 mm
8x150	100 mm	90 mm	80 mm