









d_0	Ø 8mm	Ø 8mm
	Ø 8mm	Ø 6mm







A8 $h_{nom} = 70\text{mm} \mid t_{fix2} = 0 \dots 10\text{mm}$

HUS3-HF 8	t_{fix1}	$t_{fix1} + t_{fix2}$
8x75	5 mm	5...15 mm
8x85	15 mm	15...25 mm
8x100	30 mm	30...40 mm






d_0	Ø 8mm	Ø 8mm
	Ø 8mm	Ø 6mm



B5

	h_{nom1}	h_{nom2}	h_{nom3}
HUS3-HF 8	=50mm	=60mm	=70mm
	t_{fix1}	t_{fix2}	t_{fix3}
8x65	15 mm	5 mm	-
8x75	25 mm	15 mm	5 mm
8x85	35 mm	25 mm	15 mm
8x100	50 mm	40 mm	30 mm



		d_0
		Ø 8mm

