









$d_0$	$\varnothing 10\text{mm}$







**A8**  $h_{nom}=85\text{mm} \mid t_{fix2}=0...10\text{mm}$

HUS3-H 10	$t_{fix1}$	$t_{fix1}+t_{fix2}$
10x90	5 mm	5...15 mm
10x100	15 mm	15...25 mm
10x110	25 mm	25...35 mm
10x130	45 mm	45...55 mm
10x150	65 mm	65...75 mm






$d_0$	$\varnothing 10\text{mm}$	$\varnothing 10\text{mm}$	$\varnothing 8\text{mm}$























**B5**

	$h_{nom1}$	$h_{nom2}$	$h_{nom3}$
HUS3-H 10	=55mm	=75mm	=85mm
	$t_{fix1}$	$t_{fix2}$	$t_{fix3}$
10x60	5 mm	-	-
10x70	15 mm	-	-
10x80	25 mm	5 mm	-
10x90	35 mm	15 mm	5 mm
10x100	45 mm	25 mm	15 mm
10x110	55 mm	35 mm	25 mm
10x130	75 mm	55 mm	45 mm
10x150	95 mm	75 mm	65 mm



		$d_0$
		$\varnothing 10\text{mm}$





**B5**

HUS3-H 10	$h_{nom1}$ =55mm	$h_{nom2}$ =75mm	$h_{nom3}$ =85mm
	$t_{fix1}$	$t_{fix2}$	$t_{fix3}$
10x60	5 mm	-	-
10x70	15 mm	-	-
10x80	25 mm	5 mm	-
10x90	35 mm	15 mm	5 mm
10x100	45 mm	25 mm	15 mm
10x110	55 mm	35 mm	25 mm
10x130	75 mm	55 mm	45 mm
10x150	95 mm	75 mm	65 mm